



extends your EnOcean by a new dimension

Known Bugs

by

BootUp GmbH

Sonnenbergstrasse 460
CH- 5236 Remigen Switzerland
phone: +41 56 284 09 21
fax: +41 56 284 09 22
mail: info@bootup.ch

Pending Bugs

Problem:
 Entry: Fix:
 Id:
 Statement:
 Workaround:

Solved Bugs

Problem: Weatherstation WMR918/WMR928
 Entry: 2010.03.12 Fix: V1.2.4
 Id: 2010.02.12.1
 Statement: 1. myHomeControl doesn't drive the RTS signal of the RS232.
 Therefore a NULL modem has to be used to enable the weather
 station to send data to the PC.
 2. The "new THB message" sent by new inside temperature sensor is
 not evaluated.
 Workaround: use a NULL-Modem

Problem: Sequence block
 Entry: 2010.02.08 Fix: V1.2.4
 Id: 2010.02.08.1
 Statement: The sequence block doesn't react on the up/down commands.
 Workaround: none

Problem: USB Camera
 Entry: 2009.11.17 Fix: V1.2.1
 Id: 2009.11.17.1
 Statement: The first camera listed in the list of local cameras is not operational-
 Workaround: none

Problem: Properties dialog of the PIR block, missing close button
 Entry: 2009.09.14 Fix: V12 28.09.2009
 Id: 2009.09.14.1
 Statement: In some cases the close button is missing in the properties dialog of
 the PIR blocks (red button with white cross).
 Workaround: Open a properties dialog of an other block.

Problem: Exception in Visualization Element PTM Button
 Entry: 2009.09.01 Fix: V1.2 28.09.2009
 Id: 2009.09.01.1
 Statement: Appearance "Dialog with buttons":
 In case the symbol has been clicked to open the control dialog an
 exception appears.
 Workaround: Select the appearance "Buttons".

Problem:	disconnect USB-Converter	
Entry:	2009.08.26	Fix: V1.2 Beta 28.08.2009
Id:	2009.08.26.1	
Statement:	In case a USB-Converter (USB<->RS232 or USB<->RS485) gets removed from the USB port, then myHomeControl hangs-up.	

Problem:	Single button control (toggle mode)	
Entry:	2009.08.25	Fix: V1.2 Beta 28.08.2009
Id:	2009.08.25.3	
Statement:	A switching actuator shall be controlled by a single button of a rocker switch. Therefore a toggle block is used. In case the switching actuator has been operated directly on the screen, then the toggle block loses synchronization.	

Problem:	Blind actuator from PEHA / Scenes	
Entry:	2009.08.25	Fix: V1.2 Beta 28.08.2009
Id:	2009.08.25.2	
Statement:	The blind actuator does not drive the blind to the position stored in a scene.	

Problem:	Blind actuator from PEHA	
Entry:	2009.08.25	Fix: V1.2 Beta 28.08.2009
Id:	2009.08.25.1	
Statement:	The blind actuator does not automatically drive to the end position in case the button in myHomeControl has been pressed for long time.	

Problem:	Thermokon EasySens Gateway	
Entry:	2009.08.20	Fix: V1.2 Beta 20.08.2009
Id:	2009.08.20.1	
Statement:	myHomeControl ® is not able to access the Ethernet-Gateway from Thermokon.	